
Did You Know that 60% of Pump Failures can be linked to Mis-Alignment?

Avoid Mis-Alignment Issues by Choosing Liquiflo's <u>Close-Coupled</u> Option


MIS-ALIGNED PUMP TO MOTOR



316 SS, Alloy-20 or Alloy-C Construction Precision-Machined Sturdy Cast Iron Bracket Supports Pump & Motor

Bracket shown open for demonstration only.

Available for 3 & H-Series Sealed Gear Pumps



FEATURES:

- Eliminates difficulties and inconvenience of aligning pump and motor
- Cast Iron bracket that rigidly supports
 pump & motor
- Dimensionally interchangeable with Liquiflo Mag-Drive pumps
- Available for NEMA 56C, 143/145TC & 182/184TC and IEC 71, 80 & 90 frame motors
- Excellent for OEM applications

Description



Mis-aligned pumps add excess radial loads and stresses to shafts, bearings and seals. This is one of the most common causes of premature pump failure. Liquiflo's **Close-Coupled** option was designed to eliminate the need of having to manually align the pump and motor. Using our **Close-Coupled** option, you simply bolt the pump and motor together and exact alignment is guaranteed.

Maintenance and Installation



Pumps with the **Close-Coupled** option use the same repair parts and are just as easy to rebuild as our standard models. Pump maintenance and installation is further simplified since manual pump and motor alignment is no longer required. With the **Close-Coupled** option, installation can be performed quickly and the maintenance issues associated with mis-alignment are eliminated.

Close-Coupled Option is available for pumps with Single Mechanical Seal, Double Mechanical Seal, External Mechanical Seal and Packing

Liquifl

443 North Avenue • Garwood • New Jersey • 07027 • USA tel: 908.518.0777 • fax: 908.518.1847

www.liquiflo.com

OFFICIAL UK DISTRIBUTOR: Michael Smith Engineers Limited Website: www.michael-smith-engineers.co.uk

Freephone: 0800 316 7891